

LABORATORY OF TREE-RING RESEARCH RENOVATIONS

FACILITY PROGRAM

UA Project No. 06-8727

Prepared for:

The University of Arizona
Tucson, Arizona

Phase One and Phase Two Draft May 9, 2008



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

TABLE OF CONTENTS

SE	ECTIC	ON	PAGE
Ι	PRO	OJECT SUMMARY	
	Proje	ect Narrative	1
		e Requirements	
		e Relationship Matrix	
II	PRO	DJECT SUMMARY	
	1.0	Administration	5
	2.0	Offices	
	3.0	Dry Laboratory Space	33
	4.0	Wet Laboratory Space	46
	5.0	Miscellaneous Work Rooms & Archives (Deferred)	47
	60	Common Aross	10



Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

PROJECT NARRATIVE

Scope of Work

The following program attempts to accurately develop functional and spacial requirements to renovate existing space in the West Stadium for use by the Laboratory of Tree-Ring Research (LTRR).

The current facilities for the LTRR are disjointed and located in unconnected areas of the west side of the University of Arizona football stadium and other University buildings. Through our understanding of the project users' programmatic and functional needs, we will strive to create a well-organized program that will provide for the expansion of the LTRR into the former Printing and Graphics facilities (Phase I and Phase III) and the renovation of the existing LTRR facilities located on the Ground Floor of the West Stadium – (Phase II).

M3 Engineering and Technology Corp. (M3) was retained by the University of Arizona to program spacial requirements and explore the potential scope and estimated costs for renovation to the West Stadium for the LTRR. Upon approval of the program, M3 will establish solutions that will provide a complete renovation to the level of quality that is typical for similar spaces on the University of Arizona campus.

Approach

Work on this program was fostered through meetings with Tom Swetnam, Director of the LTRR, Steve Leavitt, Associate Director, LTRR, Carl Gajdorus of the University of Arizona Facilities Design and Construction Department, and key members of the LTRR Staff.

M3 also conducted an in-depth site visit to the spaces that will be renovated. This site visit involved architects along with mechanical and electrical engineers. Through measuring, photography, and sketching, M3 was able to draw up the existing space and use it as a tool to communicate with the client. Additional information was also gathered through research and study of as-built drawings.

Using all of the information gathered, M3 was able to make informed decisions in compiling a thorough program for review by the client. This information will aid the design team in assembling a solution that will meet the programmatic and functional needs of the LTRR.

Summary

This program is formatted through a summary of spaces that includes six sections. The individual spaces within these sections are addressed in regards to function, square footage, occupancy, utilities, and equipment requirements. A size/function diagram is also included for each space.

The total programmed area for this project is 18,219 G.A.S.F (13,496 N.A.S.F). The existing area of the West Stadium to be occupied by the Laboratory of Tree Ring Research is 15,635 G.A.S.F.

Several programmed functions have been identified as being able to be deferred for inclusion in a future LTRR project.



Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

The designation of certain spaces as deferred and future allows the remaining higher priority space needs to more closely align with the available existing G.A.S.F.

The need to keep the LTRR existing offices and laboratories functioning necessitates that the renovation be accomplished in two phases.

Phase I will provide for the expansion of the LTRR into the former Printing and Graphics facilities. The programmed area for this phase is 10,469 G.A.S.F. (7,755 N.A.S.F.). An existing LTRR "Wet Laboratory" suite located within this Phase I work area will need to remain insitu during the renovation process until the completion of similar replacement space in either Phase II or the new Archive Building.

Upon completion of Phase I the LTRR Staff located in the Phase II work area will relocate into their new permanent facilities in the Phase I area.

Phase II will provide for the renovation of the remaining existing LTRR spaces. The programmed area for this phase is 4,442 G.A.S.F (3,290 N.A.S.F.).

Upon completion of Phase II the LTRR Staff will occupy this space and Phase III, renovation of the existing "Wet Laboratory" space will occur.

Acknowledgements

M3 Engineering and Technology Corp. extends our sincere thanks to all who took part in the preparation of this program. Special thanks to Tom Swetnam and Steve Leavitt for your diligent efforts to educate the Design Team as to the LTRR needs and for your patience and suggestions. The meetings and facility tours with you were extremely helpful in gathering critical information and understanding the work of the LTRR that will enrich the design of this project.



Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

SPACE REQUIREMENTS

SPACE DESCRIPTION	Number of Spaces	Occupants Per Space	Occcupancy Total	N.A.S.F. Per Space	N.A.S.F. Total	Phase I	Phase II
1.0 ADMINISTRATION							
1.01 Director's Office	1.00	1.00	1.00	210.00	210.00	210.00	0.00
1.02 Business Manager	1.00	1.00	1.00	105.00	105.00	105.00	0.00
1.03 Clerical Staff & Part-Time Student	1.00	3.00	3.00	90.00	270.00	270.00	0.00
1.04 File Room	1.00	0.00	0.00	230.00	230.00	230.00	0.00
1.05 Storage Room	1.00	0.00	0.00	80.00	80.00	80.00	0.00
1.06 Reception Area	1.00	0.00	0.00	256.00	256.00	256.00	0.00
Occupancy Total N.A.S.F. Total		<u> </u>	5.00		1,151.00	1,151.00	0.00
2.0 OFFICES	<u> </u>	.	!		1,131.00	1,151.00	0.00
2.01 Senior Faculty Offices	2.00	1.00	2.00	160.00	320.00	320.00	0.00
2.02 Principal Investigator Office - Large	4.00	1.00	4.00	160.00	640.00	480.00	160.00
2.03 Principal Investigator Office - Small	5.00	1.00	5.00	130.00	650.00	390.00	260.00
2.04 Post-Doctorate / Associate Office	6.00	1.00	6.00	130.00	780.00	650.00	130.00
2.05 Visitor Office	3.00	1.00	3.00	130.00	390.00	0.00	390.00
2.06 Graduate Student Cubicle	10.00	1.00	10.00	55.00	550.00	550.00	0.00
2.07 Shared Conference	5.00	0.00	0.00	144.00	720.00	576.00	144.00
2.08 Common Storage	1.00	0.00	0.00	300.00	300.00	0.00	300.00
Occupancy Total			30.00				
N.A.S.F. Total					4,350.00	2,966.00	1,384.00
3.0 DRY LABORATORY SPACE		•					•
3.01 Hydroclimatology Laboratory	1.00	0.00	0.00	800.00	800.00	800.00	0.00
3.02 Dendrochemistry Laboratory	1.00	0.00	0.00	800.00	800.00	800.00	0.00
3.03 Dendroecology Laboratory	1.00	0.00	0.00	800.00	800.00	0.00	800.00
3.04 Dendroarcheology Laboratory	1.00	0.00	0.00	525.00	525.00	525.00	0.00
3.05 Dendroclimatology Laboratory	1.00	0.00	0.00	525.00	525.00	525.00	0.00
3.06 Measuring Laboratory/Densitometry	1.00	0.00	0.00	525.00	525.00	0.00	525.00
3.07 Entomology Laboratory	1.00	0.00	0.00	400.00	400.00	0.00	400.00
Occupancy Total			0.00				
N.A.S.F. Total					4,375.00	2,650.00	1,725.00
4.0 WET LABORATORY SPACE	1						
4.01 Common Wet Laboratory - (Deferred)	1.00	0.00	0.00	600.00	600.00	0.00	0.00
4.02 X-Ray Denisitometry Laboratory - (now 3.06)							
4.03 X-Ray Room (Existing) - (now 3.06)							
4.04 Optical Microscopy Laboratory - (now 3.06)							
4.05 Grinding Workroom - (now 3.02)							
Occupancy Total		 	0.00		600.00	0.00	0.00
N.A.S.F. Total 5.0 MISCELLANEOUS WORK ROOMS & ARCHIVES					600.00	0.00	0.00
5.01 Archival and Wood Preparation Shop - (Deferred)		0.00	0.00	384.00	384.00	0.00	0.00
5.01 Equipment Storage / Maintenance - (Dererred)	1.00	0.00	0.00	384.00 156.00	156.00	0.00	0.00
5.03 Mechanical Equipment Room - (Deferred)	1.00	0.00	0.00	36.00	36.00	0.00	0.00
Occupancy Total		0.00	0.00	30.00	30.00	0.00	0.00
N.A.S.F. Total		1	0.00		576.00	0.00	0.00
6.0 COMMON AREAS					370.00	0.00	0.00
6.01 Multi-Purpose Room - (Deferred)	1.00	0.00	0.00	875.00	875.00	0.00	0.00
6.02 Library/Shared Conference Room - (Deferred)	1.00	0.00	0.00	400.00	400.00	0.00	0.00
6.03 Staff Lounge	1.00	0.00	0.00	200.00	200.00	0.00	200.00
6.04 Copy / Printer Room / Mail Room	1.00	0.00	0.00	140.00	140.00	140.00	0.00
6.05 Men / Women Restrooms and Showers	1.00	0.00	0.00	350.00	350.00	350.00	0.00
6.06 Gender Neutral Restroom	1.00	0.00	0.00	125.00	125.00	0.00	125.00
6.07 Janitor's Closet	1.00	0.00	0.00	80.00	80.00	80.00	0.00
6.08 Electrical Equipment Room	1.00	0.00	0.00	74.00	74.00	74.00	0.00
6.09 UITS Room	1.00	0.00	0.00	100.00	100.00	100.00	0.00
6.10 Server Room	1.00	0.00	0.00	100.00	100.00	100.00	0.00
Occupancy Total			0.00				
N.A.S.F. Total					2,444.00	844.00	325.00
Occupancy Total			35.00				
Program N.A.S.F. Total					13,496.00	7,611.00	3,434.00
Program G.A.S.F. Total (N.A.S.F. + 35%)					18,219.60	10,274.85	4,635.90
Existing G.A.S.F. at Renovation Space					15,635.00	11,335.00	4,300.00

Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

SPACE RELATIONSHIP MATRIX

SPACE RELATIONSHIP MATRIX

		_					
1.0	ADMINISTRATION		_				
2.0	OFFICES	3					
3.0	DRY LABORATORY SPACE	3	2		_		
4.0	WET LABORATORY SPACE	3	2	3		_	
5.0	MISC. WORK ROOMS & ARCHIVES	3	3	2	2		
6.0	COMMON AREAS	2	2	3	3	3	
1 MU 2 SHO	ORITY KEY ST BE JOINED DULD BE ADJACENT STRONG RELATIONSHIP	1.0 ADMINISTRATION	2.0 OFFICES	3.0 DRY LABORATORY SPACE	4.0 WET LABORATORY SPACE	5.0 MISC. WORK ROOMS & ARCHIVES	6.0 COMMON AREAS



Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

1.0 ADMINISTRATION

1.01	Director's Office
1.02	Business Manager
1.03	Clerical Staff & Part-Time Student
1.04	File Room
1.05	Storage Room
1.06	Reception Area



Renovations U. of A. Project No.: 06-8727 Tucson, Arizona May 9, 2008

1.0 ADMINISTRATION

SPACE NAME: 1.01 Director's Office

FUNCTION: Office space for the Director. **PLUMBING/PROCESS PIPING**:

SERVICE: N/A
SPECIAL: N/A
FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: 180 **TEMP/HUMD**: Air Conditioned Environment.

REQ'D: 210 (Per A.B.O.R. Space Standards)

OCCUPANTS: OTHER:

EXISTING: 1

REQ'D: 1 (Swetnam)

ENVIRONMENT:

FLOOR: Carpet

WALL: Gypsum Board
CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.

INGRESS/EGRESS: Corridor / Clerical Staff

and part-time student.

SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Telephone and Data

ELECTRICAL:

LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets

GROUNDING:

M3-PN08004




U. of A. Project No.: 06-8727

May 9, 2008

M3-PN08004

1.0 ADMINISTRATION

SPACE NAME: 1.01 Director's Office							
FURNITURE/EQU	FURNITURE/EQUIPMENT:						
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D				
	Desk Chairs		5				
	30" x 60" Desk		1				
	Built -In Work Counter		1				
	18" x 29" Vertical File Cabinets		4				
	Built-In Book Shelving		1				
	Conference Table		1				





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

1.0 ADMINISTRATION

SPACE NAME: 1.02 Business Manager

FUNCTION: Office space for the **PLUMBING/PROCESS PIPING**:

Business Manager SERVICE: N/A SPECIAL: N/A

FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: **TEMP/HUMD**: Air Conditioned Environment.

REQ'D: 105 (Per A.B.O.R. Space Standards)

OCCUPANTS: OTHER:

EXISTING:

REQ'D: 1 Business Manager (Martinez)

ENVIRONMENT:

FLOOR: Carpet

WALL: Gypsum Board
CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.
INGRESS/EGRESS: Reception
SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Telephone and Data

ELECTRICAL:

LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets




U. of A. Project No.: 06-8727

May 9, 2008

M3-PN08004

1.0 ADMINISTRATION

SPACE NAME: 1.02 Business Manager							
FURNITURE/EQU	FURNITURE/EQUIPMENT:						
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D				
	Desk with 45" computer corner		1				
	Desk Chair		1				
	P.C.		1				





U. of A. Project No.: 06-8727 Tucson, Arizona

May 9, 2008

M3-PN08004

1.0 ADMINISTRATION

SPACE NAME: 1.03 Clerical Staff and Part-Time Student

FUNCTION: Office space for the Clerical Staff PLUMBING/PROCESS PIPING:

> and part-time student. **SERVICE:** N/A Mail Distribution Point. SPECIAL: N/A

> > FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: 320 **TEMP/HUMD:** Air Conditioned Environment.

REQ'D: 270 (Per A.B.O.R. Space Standards)

OCCUPANTS: OTHER:

EXISTING:

REQ'D: 3 (1 Acct., 1 Admin. Assist.,

1 part-time student).

ENVIRONMENT:

FLOOR: Carpet

WALL: Gypsum Board **CEILING:** Lay-In Acoustic CEILING HEIGHT: 8'-0" min. **INGRESS/EGRESS:** Reception **SECURITY:** Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Telephone and Data

ELECTRICAL:


LIGHTING: General Fluorescent POWER: 110 V Power Outlets



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

1.0 ADMINISTRATION

SPACE NAME: 1.03 Clerical Staff and Part-Time Student				
FURNITURE/EQU	JIPMENT:			
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D	
	Desk with 45° computer corner		3	
	Desk Chair		3	
	Reception Desk		1	
	P.C.		3	
	12" x 12" Stacked Mail Lockers		60+	





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

1.0 ADMINISTRATION

SPACE NAME: 1.04 File Room

FUNCTION: Filing area with desk for the **PLUMBING/PROCESS PIPING**:

Tree-Ring Society. SERVICE: N/A SPECIAL: N/A

FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: <u>HVAC</u>:

EXISTING: 165 **TEMP/HUMD**: Air Conditioned Environment.

REQ'D: 230

OCCUPANTS: OTHER:

EXISTING: N/A **REQ'D**: N/A

ENVIRONMENT:

FLOOR: Vinyl Composition Tile (VCT)

WALL: Gypsum Board
CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.

INGRESS/EGRESS: Clerical Staff and

part-time student.

SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: N/A

ELECTRICAL:

LIGHTING: General Fluorescent


POWER: 110 V Power Outlet at Desks



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

1.0 ADMINISTRATION

SPACE NAME: 1.04 File Room				
FURNITURE/EQUIPMENT:				
TAG NO.	DESCRIPTION	QTY EXISTING	<u>REQ'D</u>	
	30" x 60" Desks		2	
	Desk Chairs		2	
	18" x 29" - 5 Drawer Vertical Files		20	
	Typewriter		1	





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

1.0 ADMINISTRATION

SPACE NAME: 1.05 Storage Room

FUNCTION: Space for general storage. **PLUMBING/PROCESS PIPING**:

SERVICE: Cold Water; Sewer.

SPECIAL: N/A
FIXTURES: Sink

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: ± 80 **TEMP/HUMD**: Air Conditioned Environment.

REQ'D: 80

<u>OCCUPANTS</u>: <u>OTHER</u>:

EXISTING: N/A **REQ'D**: N/A

ENVIRONMENT:

FLOOR: Vinyl Composition Tile (VCT)

WALL: Gypsum Board
CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.

INGRESS/EGRESS: Clerical Staff and

part-time student.

SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: N/A

ELECTRICAL:


LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

1.0 ADMINISTRATION

SPACE NAME: 1.05 Storage Room					
FURNITURE/EQU	FURNITURE/EQUIPMENT:				
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D		
	24" x 24" Storage Shelves		6		
	Base Cabinet		2		
	Fax Machine		1		





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

1.0 ADMINISTRATION

SPACE NAME: 1.06 Reception Area

FUNCTION: Entry and reception area for the **PLUMBING/PROCESS PIPING**:

Public. SERVICE: N/A

SPECIAL: N/A FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: 0 **TEMP/HUMD**: Air Conditioned Environment.

REQ'D: 256

OCCUPANTS: OTHER:

EXISTING: N/A REQ'D: N/A

ENVIRONMENT:

FLOOR: Carpet

WALL: Gypsum Board
CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.
INGRESS/EGRESS: Exterior

SECURITY: Lockable Exterior Door

COMMUNICATION:

TELEPHONE/DATA: Telephone Outlet

ELECTRICAL:


LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

1.0 ADMINISTRATION

SPACE NAME: 1.06 Reception Area				
FURNITURE/EQU	FURNITURE/EQUIPMENT:			
TAG NO.	DESCRIPTION	QTY EXISTING	<u>REQ'D</u>	
	Chairs		3	





U. of A. Project No.: 06-8727 May 9, 2008

M3-PN08004

2.0 OFFICES

2.01	Senior Facility Offices (2)
2.02	Principal Investigator Office – Large (3)
2.03	Principal Investigator Office - Small (6)
2.04	Post-Doctorate / Associate Office (5)
2.05	Visitor Office (3)
2.06	Graduate Student Cubicle (10)
2.07	Shared Conference (5)
2.08	Common Storage



Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

2.0 OFFICES

SPACE NAME: 2.01 Senior Faculty Offices (2)

FUNCTION: Office space for Senior Faculty **PLUMBING/PROCESS PIPING**:

Principal Investigators. SERVICE: N/A

SPECIAL: N/A
FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: Varies **TEMP/HUMD:** Air Conditioned Environment.

REQ'D: 160 (Per A.B.O.R. Space Standards)

OCCUPANTS: OTHER: unnecessary

EXISTING: -

REQ'D: 2 (1 each office)

(Leavitt, Hughes)

ENVIRONMENT:

FLOOR: Carpet

WALL: Gypsum Board

CEILING: Lay-In Acoustic

CEILING HEIGHT: 8'-0" min.

INGRESS/EGRESS: Corridor / Departmental Offices

SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Telephone and Multiple Data

Connections

ELECTRICAL:

LIGHTING: General Fluorescent / Incandescent


POWER: 110 V Power Outlets



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

2.0 OFFICES

SPACE NAME: 2.01 Senior Faculty Offices (2)					
FURNITURE/EQU	FURNITURE/EQUIPMENT:				
TAG NO.	DESCRIPTION	QTY EXISTING	<u>REQ'D</u>		
	Built-In Book Shelving		1		
	Desk Chairs		3		
	3'-0" x 6'-0" Work Table		1		
	Built-In Shelves / Work Counter		1		
	18" x 29" Vertical File Cabinets		2		





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

2.0 OFFICES

SPACE NAME: 2.02 Principal Investigator Office - Large (4)

FUNCTION: Office space for Principal Investigators. **PLUMBING/PROCESS PIPING**:

SERVICE: N/A
SPECIAL: N/A
FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: Varies **TEMP/HUMD**: Air Conditioned Environment.

REQ'D: 160 (Per A.B.O.R. Space Standards)

OCCUPANTS: OTHER: unnecessary

EXISTING: -

REQ'D: 3 (1 each office)

(Touchan, Sheppard, Panyushkina)

ENVIRONMENT:

FLOOR: Carpet

WALL: Gypsum Board
CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.

INGRESS/EGRESS: Corridor / Departmental Offices

SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Telephone and Multiple Data

Connections

ELECTRICAL:

LIGHTING: General Fluorescent / Incandescent

POWER: 110 V Power Outlets




U. of A. Project No.: 06-8727 May 9, 2008

M3-PN08004

2.0 OFFICES

SPACE NAME: 2.02 Principal Investigator Office - Large (4)					
FURNITURE/EQU	FURNITURE/EQUIPMENT:				
TAG NO.	DESCRIPTION	QTY EXISTING	<u>REQ'D</u>		
	Built-In Book Shelving		1		
	Desk Chairs		3		
	3'-0" x 6'-0" Work Table		1		
	Built-In Shelves / Work Counter		1		
	18" x 29" Vertical File Cabinets		2		
	P.C. and Printer		1		





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

2.0 OFFICES

SPACE NAME: 2.03 Principal Investigator Offices - Small (6)

FUNCTION: Office space for Principal Investigators **PLUMBING/PROCESS PIPING**:

SERVICE: N/A
SPECIAL: N/A

FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: ± 115 **TEMP/HUMD**: Air Conditioned Environment.

REQ'D: 130 (per A.B.O.R. Space Standards)

OCCUPANTS: OTHER:

EXISTING: -

REQ'D: 6 (1 each office)

(Woodhouse, Meko, Falk, Lynch,

Swetnam, Towner)

ENVIRONMENT:

FLOOR: Carpet
WALL: Gypsum Board

CEILING: Lay-In Acoustic

CEILING HEIGHT: 8'-0" min.

INGRESS/EGRESS: Corridor / Departmental Offices

SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Telephone Data Connections

ELECTRICAL:

LIGHTING: General Fluorescent / Incandescent


POWER: 110 V Power Outlets



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

2.0 OFFICES

SPACE NAME: 2.03 Principal Investigator Offices – Small (6)					
FURNITURE/EQU	FURNITURE/EQUIPMENT:				
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D		
	Built-In Book Shelving		1		
	Desk Chair		1		
	3'-0" x 6'-0" Work Table		1		
	Built-In Shelves / Work Counter		1		
	18" x 29" Vertical File Cabinets		1		
	P.C. and Printer		1		





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

2.0 OFFICES

SPACE NAME: 2.04 Post-Doctorate / Associate Office (6)

FUNCTION: Office space for Post-Doctorate / **PLUMBING/PROCESS PIPING:**

Associates. SERVICE: N/A

SPECIAL: N/A FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: ± 115 **TEMP/HUMD**: Air Conditioned Environment.

REQ'D: 130 (per A.B.O.R. Space Standards)

OCCUPANTS: OTHER:

EXISTING: -

REQ'D: 5 (1 each office)

ENVIRONMENT:

FLOOR: Carpet

WALL: Gypsum Board
CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.

INGRESS/EGRESS: Corridor / Departmental

Offices

SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Telephone Data Connections

ELECTRICAL:

LIGHTING: General Fluorescent / Incandescent


POWER: 110 V Power Outlets



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

2.0 OFFICES

SPACE NAME: 2.04 Post-Doctorate / Associate Office (6)					
FURNITURE/EQU	FURNITURE/EQUIPMENT:				
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D		
	Built-In Book Shelving		1		
	Desk Chair		1		
	3'-0" x 6'-0" Work Table		1		
	Built-In Shelves / Work Counter		1		
	18" x 29" Vertical File Cabinets		1		
	P.C. and Printer		1		





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

2.0 OFFICES

SPACE NAME: 2.05 Visitor Office (3)

FUNCTION: Office space for visiting Faculty

Researchers

PLUMBING/PROCESS PIPING:

SERVICE: N/A
SPECIAL: N/A

FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: ± 115 **TEMP/HUMD**: Air Conditioned Environment.

REQ'D: 130 (per A.B.O.R. Space Standards)

<u>OCCUPANTS</u>: <u>OTHER</u>:

EXISTING: -

REQ'D: 5 (1 each office)

ENVIRONMENT:

FLOOR: Carpet

WALL: Gypsum Board
CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.

INGRESS/EGRESS: Corridor / Departmental

Offices

SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Telephone Data Connections

ELECTRICAL:

LIGHTING: General Fluorescent / Incandescent

POWER: 110 V Power Outlets




U. of A. Project No.: 06-8727 May 9, 2008

M3-PN08004

2.0 OFFICES

SPACE NAME: 2.05 Visitor Office (3)					
FURNITURE/EQU	FURNITURE/EQUIPMENT:				
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D		
	Built-In Book Shelving		1		
	Desk Chair		1		
	3'-0" x 6'-0" Work Table		1		
	Built-In Shelves / Work Counter		1		
	18" x 29" Vertical File Cabinets		1		
	P.C. and Printer		1		





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

2.0 OFFICES

SPACE NAME: 2.06 Graduate Student Cubicle (10)

FUNCTION: Office space for Graduate Students. **PLUMBING/PROCESS PIPING**:

SERVICE: N/A
SPECIAL: N/A
FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: ± 30 **TEMP/HUMD**: Air Conditioned Environment.

REQ'D: 55 (per A.B.O.R. Space Standards)

OCCUPANTS: OTHER:

EXISTING: -

REQ'D: 10 (1 each space)

ENVIRONMENT:

FLOOR: Carpet

WALL: Gypsum Board
CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.
INGRESS/EGRESS: Corridor

SECURITY: N/A

COMMUNICATION:

TELEPHONE/DATA: Telephone and Data

ELECTRICAL:


LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

2.0 OFFICES

SPACE NAME: 2.06 Graduate Student Cubicle (10)				
FURNITURE/EQU	JIPMENT:			
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D	
	Built-In Shelves / Work Counter		1	
	Desk Chair		1	
	Lockable Storage		1	
	P.C.		1	





Renovations U. of A. Project No.: 06-8727 Tucson, Arizona May 9, 2008

2.0 OFFICES

SPACE NAME: 2.07 Shared Conference (5)

FUNCTION: Common area within office suites **PLUMBING/PROCESS PIPING**:

for meetings and storage. **SERVICE**: N/A

SPECIAL: N/A
FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: TEMP/HUMD: Air Conditioned Environment.

REQ'D: 144

OCCUPANTS: OTHER:

EXISTING: REQ'D: 0

ENVIRONMENT:

FLOOR: Carpet

WALL: Gypsum Board
CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.

INGRESS/EGRESS: PI Offices, Post Doc / Assoc.

Offices, Corridor

SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Telephone & Data

ELECTRICAL:

LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets

GROUNDING:


M3-PN08004



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

2.0 OFFICES

SPACE NAME: 2.07 Shared Conference (5)					
FURNITURE/EQU	FURNITURE/EQUIPMENT:				
TAG NO.	DESCRIPTION	QTY EXISTING	<u>REQ'D</u>		
	3'-6" Diameter Table		1		
	Chairs		4		
	Built-In Book Shelves		1		
	18" x 29" Vertical File Cabinets		4		
	Whiteboard		1		





Renovations U. of A. Project No.: 06-8727 Tucson, Arizona May 9, 2008

2.0 OFFICES

SPACE NAME: 2.08 Common Storage

FUNCTION: Space for general storage. **PLUMBING/PROCESS PIPING**:

Field equipment storage. **SERVICE:** N/A

SPECIAL: N/A FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: **TEMP/HUMD**: Air Conditioned Environment.

REQ'D: 300

<u>OCCUPANTS</u>: <u>OTHER</u>:

EXISTING: N/A REQ'D: N/A

ENVIRONMENT:

FLOOR: Sealed Concrete **WALL**: Gypsum Board

CEILING: Exposed Structure CEILING HEIGHT: 8'-0" min. INGRESS/EGRESS: Corridor SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: N/A

ELECTRICAL:

LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets

GROUNDING:

M3-PN08004



U. of A. Project No.: 06-8727 May 9, 2008

M3-PN08004

2.0 OFFICES


SPACE NAME: 2.08 Common Storage

FURNITURE/EQUIPMENT:

TAG NO. DESCRIPTION QTY EXISTING REQ'D

24" x 24" Storage Shelves

10





U. of A. Project No.: 06-8727 May 9, 2008

M3-PN08004

3.0 DRY LABORATORY SPACE

3.01	Hydroclimatology Laboratory
3.02	Dendrochemistry / Geological Applications Laboratory
3.03	Dendroecology Large Sample Laboratory
3.04	Dendroarcheology Laboratory
3.05	Dendroclimatology Laboratory
3.06	Measuring Laboratory / Densitometry
3 07	Entomology Laboratory



Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.01 Hydroclimatology Laboratory

FUNCTION: Dry Laboratory space for analysis of **PLUMBING/PROCESS PIPING**:

small Tree-Ring samples. **SERVICE:** Hot and cold water; Sewer

SPECIAL: N/A

FIXTURES: Double Basin Sink with Eyewash and

Sediment Trap

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: ± 260 - 360 TEMP/HUMD: Air Conditioned Environment

REQ'D: 800

OCCUPANTS: OTHER:

EXISTING: – Vacuum for fine dust

REQ'D: 9 Work Stations (central system)

1 P.I. (large office) – Touchan

2 P.I. (small office) - Woodhouse, Meko

0 Post Docs.

ENVIRONMENT:

FLOOR: Vinyl Composition Tile (VCT) **WALL**: Gypsum Board with Epoxy Paint

CEILING: Lay-In Acoustic CEILING HEIGHT: 8'-0" min. INGRESS/EGRESS: Corridor

SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Multiple Telephone and Data

Connections

ELECTRICAL:

LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets




U. of A. Project No.: 06-8727 May 9, 2008 Tucson, Arizona

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.01 Hydroclimatology Laboratory			
FURNITURE/EQU	IIPMENT:		
TAG NO.	<u>DESCRIPTION</u>	QTY EXISTING	REQ'D
	Built-In Work Counter (2'-6" deep)		L.F.
	3'-0" x 2'-0" x 6'-6" H. Metal Storage Cabinets		3
	18" Deep Overhead Storage Shelving		L.F.
	Small Refrigerator under counter		1
	Chairs		9
	5'-0" x 2'-6" Measuring Stations (Computer)		4
	5'-0" x 2'-0" Microscope Stations		4
	5'-0" x 2'-0" PC & Printer Station		1
	36" x 48" Marker Boards		2
	4'-0" x 8'-0" Built-in Work Table with Elec. Outle	t	2
	Countertop Microwave Oven		1

SIZE / FUNCTIONAL DIAGRAM:



3.01 - HYDROCLIMATOLOGY LABORATORY

M3-PN08004



Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.02 Dendrochemistry / Geological Applications Laboratory

FUNCTION: Dry Laboratory space for **PLUMBING/PROCESS PIPING**:

Tree-Ring samples. Enclosed grinding SERVICE: Hot and cold water; Sewer

area to Homogenize Samples. SPECIAL:

FIXTURES: Double basin Sink 10'-12" deep with

SQUARE FOOTAGE REQUIREMENTS: Eyewash and Sediment Trap

EXISTING: <u>HVAC</u>:

REQ'D: 800 **TEMP/HUMD:** Air Conditioned Environment.

OCCUPANTS:

EXISTING: OTHER:

REQ'D: 9 Work Stations Vacuum for fine dust

1 Senior Faculty – Leavitt 1 P.I. (large office) - Sheppard (central system)

2 Post Docs Sound insulation in Grinding Room walls

ENVIRONMENT:

FLOOR: Vinyl Composition Tile (VCT) **WALL**: Gypsum Board with Epoxy Paint

CEILING: Lay-In Acoustic (Gypsum Board in

Grinding Room)

CEILING HEIGHT: 8'-0" min.
INGRESS/EGRESS: Corridor
SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Multiple Telephone and Data

Connections

ELECTRICAL:


LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets

Renovations U. of A. Project No.: 06-8727 Tucson, Arizona May 9, 2008

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.02 Dendrochemistry / Geological Applications Laboratory			
FURNITURE/EQU	JIPMENT:		
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D
	Built-In Work Counter (2'-6" deep)		L.F.
	12" Deep Storage Shelving (Books)		25 L.F.
	18" Deep Storage Shelving		110 L.F.
	Chairs		9
	3'-0" x 1'-0" x 6'-6" H. Metal Storage Shel	lving	10
	5'-0" x 2'-6" Balance Station		1
	5'-0" x 2'-6" Scope / Measuring / Computer		1
	5'-0" x 2'-6" Scope / Camera / Monitor		2
	5'-0" x 2'-6" PC and printer		3
	5'-0" x 2'-6" I.A. System Station		1
	Microwave (counter top)		1
	Half-size Refrigerator (under counter)		1
	7'-0" x 2'-6" Grinding Station (Mill)		1
	Filing Cabinets		6
	36" x 48" Marker Board		2
	36" x 48" Cork Boards		2
	4'-0" x 8'-0" Sample Layout Table		2
	Drying Oven (counter top)		1

SIZE / FUNCTIONAL DIAGRAM:



M3-PN08004



Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.03 Dendroecology / Large Sample Laboratory

FUNCTION: Dry Laboratory space for analysis of

Large Tree-Ring samples and

Entomological Analysis

PLUMBING/PROCESS PIPING:

SERVICE: Hot and cold water; Sewer

SPECIAL:

FIXTURES: Double Basin (1 deep) Utility Sink

with Eyewash and Sediment Trap

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: TEMP/HUMD: Air Conditioned Environment.

REQ'D: 800

OCCUPANTS: OTHER:

EXISTING: Vacuum for fine dust

REQ'D: 10 Work Stations (Central system)

2 P.I (small office) - Falk, Swetnam

ENVIRONMENT:

FLOOR: Vinyl Composition Tile (VCT) **WALL**: Gypsum Board with Epoxy Paint

CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.
INGRESS/EGRESS: Corridor
SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Multiple Telephone and Data

Connections

ELECTRICAL:

LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets




Renovations U. of A. Project No.: 06-8727 Tucson, Arizona May 9, 2008

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.03 Dendroecology / Large Sample Laboratory			
FURNITURE/EQ	UIPMENT:		
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D
	Built-In Work Counter (2'-6" deep)		L.F.
	4'-0" x 8'-0" Work Table (can be work	stations)	2
	Chairs		10
	5'-0" x 2'-6" Microscope Stations		5
	5'-0" x 2'-6" PC and Printer Stations		3
5'-0" x 2'-6" Measuring Machine / PC Station		1	
	5'-0" x 2'-6" Drying and Microgram Balance and Weighing Station		1
36" x 48" Cork Board		1	
36" x 48" White Board			1
	24" Deep Large Specimen Storage S		100 L.F.
18" Deep Core / Small Specimen Storage Shelves		rage Shelves	80 L.F.
2'-0" x 4'-0" x 7'-0" Field Gear Storage Cabinets (remote, 2.08)		3	
	Case for Hanging Maps (size 18"Dx36"Wx48"H)		1
	Filing Cabinets (lateral)		2
	Drying Oven		1

SIZE / FUNCTIONAL DIAGRAM:



M3-PN08004



Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.04 Dendroarcheology Laboratory

FUNCTION: Dry Laboratory Space for Archeology. **PLUMBING/PROCESS PIPING**:

Enclosed "Dirty" area for two SERVICE: Hot and cold water; Sewer

Microscope Stations. SPECIAL:

FIXTURES: Double Basin Utility Sink with

SQUARE FOOTAGE REQUIREMENTS: Eyewash and Sediment Trap

EXISTING:

REQ'D: 525 **HVAC**:

TEMP/HUMD: Air Conditioned Environment.

OCCUPANTS:

EXISTING:

REQ'D: 6 Work Stations OTHER:

1 P.I. (large office) – Panyushkina 1 P.I. (small office) - Towner Vacuum for fine dust

1 Post Doc. (central system)

ENVIRONMENT:

FLOOR: Vinyl Composition Tile (VCT) **WALL**: Gypsum Board with Epoxy Paint

CEILING: Lay-In Acoustic (Gypsum Board in

"Dirty Area")

CEILING HEIGHT: 8'-0" min.
INGRESS/EGRESS: Corridor
SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Multiple Telephone and Data

connections

ELECTRICAL:

LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets




Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.04 Dendroarcheology Laboratory			
FURNITURE/EQU	JIPMENT:		
TAG NO.	<u>DESCRIPTION</u>	QTY EXISTING	REQ'D
	Built-In Work Counter (2'-6" deep)		L.F.
	4'-0" x 8'-0" Sample Prep. Table (o	ne in dirty area)	2
	18" Deep Wood Sample Storage S	helving (heavy duty)	L.F.
	18" x 36" x 84" H. Storage Cabinet		4
	Chairs		7
	5'-0" x 2'-6" Microscope Station (dirty area)		2
	5'-0" x 2'-6" PC and Printer Station		2
	5'-0" x 2'-6" Measuring System and	Microscope	2
	36" x 48" Marker Board		1
	18" x 48" Cork Board		1
	Filing Cabinets 2-drawer high (under counter)		5
12" x 36" x 84" H. Book Case		2	
	10" x 24" x 24" Open Shelve Unit (c	over counter)	7
	12" x 24" x 30" Open Shelve Unit (c	over counter)	7





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.05 Dendroclimatology Laboratory

FUNCTION: Dry Laboratory space for basic **PLUMBING/PROCESS PIPING**:

Dendrochronology and Wood Anatomy SERVICE: Hot and cold water; Sewer

SPECIAL:

TEMP/HUMD: Air Conditioned Environment.

SQUARE FOOTAGE REQUIREMENTS: FIXTURES: Double Sink with Eyewash and

EXISTING: Sediment Trap

REQ'D: 525 **HVAC**:

OCCUPANTS: Filter out dust (not a clean room)

<u>OTHER</u>:

REQ'D: 6 Work Stations Vacuum for fine dust (central system)

1 Senior Faculty (Hughes) * Proximity to Micro Densitometry equipment is

2 Post Docs. desired.

Prefer P.I, office close to Lab if possible.

ENVIRONMENT: * Provide optical table or isolation slab for I.A.

FLOOR: Vinyl Composition Tile (VCT)

System and Wood Anatomy Microscope

WALL: Gypsum Board with Epoxy Paint

CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.
INGRESS/EGRESS: Corridor
SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Multiple Telephone and Data

Connections

ELECTRICAL:

LIGHTING: General Fluorescent

Strong light at work surface – 100 F.C.

Light spectrum - not critical


POWER: 110 V Power Outlets

U. of A. Project No.: 06-8727 May 9, 2008 Tucson, Arizona

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.05 Dendroclimatology Laboratory				
FURNITURE	FURNITURE/EQUIPMENT:			
TAG NO.	<u>DESCRIPTION</u> <u>QTY EXISTIN</u>	G <u>REQ'D</u>		
	Built-In Work Counter (2'-6" deep)	L.F.		
	4'-0" x 8'-0" Work Table	1		
	18" Sample Storage Shelving	<u>80</u> L.F.		
	Chairs	10		
	4'-0" x 2'-6" Binoc Microscope Station	1		
	6'-0" x 2'-6" Measuring System Station	1		
	3'-0" x 2'-6" Measuring System Printer	1		
	4'-0" x 2'-6" Wood Anatomy Microscope Station (anti-vibration	required) 1		
	4'-0" x 2'-6" Transmitted Light (I.A.) System & Computer	1		
	Station (anti-vibration required)			
	3'-0" x 2'-6" Microtomes (counter top)	3		
	3'-0" x 2'-6" Computer Station	1		
	4'-0" x 2'-0" Light Table Work Station	1		
	Filing Cabinets	2		

SIZE / FUNCTIONAL DIAGRAM:



3.05 - DENDROCLIMATOLOGY LABORATORY

M3-PN08004



U. of A. Project No.: 06-8727 May 9, 2008 Tucson, Arizona

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.06 Measuring Laboratory / Densitometry

FUNCTION: Dry Laboratory space for measuring PLUMBING/PROCESS PIPING:

> SERVICE: N/A samples. Densitometry Unit will be

> located in this lab. SPECIAL: FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: **TEMP/HUMD:** Air Conditioned Environment.

REQ'D: 525

OCCUPANTS: OTHER:

EXISTING:

REQ'D: 3 Work Stations

ENVIRONMENT:

FLOOR: Vinyl Composition Tile (VCT) WALL: Gypsum Board with Epoxy Paint

CEILING: Lay-In Acoustic CEILING HEIGHT: 8'-0" min. **INGRESS/EGRESS:** Corridor **SECURITY:** Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Multiple Telephone and Data

Connections

ELECTRICAL:

LIGHTING: General Fluorescent POWER: 110 V Power Outlets

GROUNDING:


M3-PN08004



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.06 Measuring Laboratory / Densitometry			
FURNITURE/EQU	JIPMENT:		
TAG NO.	DESCRIPTION	QTY EXISTING	<u>REQ'D</u>
	Built-In Work Counter (2'-6" deep)		L.F.
	4'-0" x 8'-0" Work Table		1
	24" x 48" Storage Shelving		2
	Chairs		3
	5'-0" x 2'-6" Measuring Station / Computer		3
	6'-0"L x 3'-0"W x 6'-0"H Densitometry Unit		1





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.07 Entomology Laboratory

FUNCTION: Dry Laboratory space for Entomology

(for use by the U.S.F.S.).

PLUMBING/PROCESS PIPING:

SERVICE: Cold water; Sewer

SPECIAL: N/A

FIXTURES: Dishwasher, 2 Comp. sink

SQUARE FOOTAGE REQUIREMENTS: With Eyewash and Sediment Trap.

EXISTING: 400 Refrigerator & Chest Freezer

REQ'D: 400

HVAC:

OCCUPANTS: TEMP/HUMD: Air Conditioned Environment

EXISTING:

REQ'D: 2 Workstations OTHER:

1 P.I. (large office) - Lynch

1 Post-Doc.

ENVIRONMENT:

FLOOR: Vinyl Composition Tile (VCT) **WALL**: Gypsum Board with Epoxy Paint

CEILING: Lay-in Acoustic
CEILING HEIGHT: 8'-0" min.
INGRESS/EGRESS: Corridor
SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Multiple Telephone and Data

connections

ELECTRICAL:


LIGHTING: General Fluorescent **POWER:** 110V Power Outlets



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

3.0 DRY LABORATORY SPACE

SPACE NAME: 3.07 Entomology Laboratory			
FURNITURE/EQ	UIPMENT:		
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D
	Built-in Work Counter		1
	4'-0" x 8'-0' Work Table		2
	24' x 48" Storage Shelving		2
	Tabletop Drying Oven		1
	2-Burner Cook Top		1
	Measuring & Microscopes Counter		1
	Refrigerator		1
	Chest Freezer		1
	Chairs		3
SIZE / FUNCTIO	NAL DIAGRAM:		





M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

4.0 WET LABORATORY SPACE

4.01	Common Wet Laboratory (Deferred)
4.02	X-Ray Densitometry Laboratory - (now 3.06)
4.03	X-Ray Room (Existing) - (now 3.06)
4.04	Optical Microscopy Laboratory - (now 3.06)
4.05	Grinding Workroom - (now 3.02)



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

5.0 MISCELLANEOUS WORK ROOMS & ARCHIVES

5.01	Archival and Wood Preparation Shop - (Deferred)
5.02	Equipment Storage / Maintenance - (Deferred)
5.03	Mechanical Equipment Room - (Deferred)



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 **COMMON AREAS**

6.01	Multi-Purpose Room - (Deferred)
6.02	Library / Shared Conference Room (Deferred)
6.03	Staff Lounge
6.04	Copy / Printer Room
6.05	Men / Women Restroom and Showers
6.06	Gender Neutral Restroom
6.07	Janitor's Closet
6.08	Electrical Equipment Room
6.09	UITS Room
6 10	Server Room



Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.03 Staff Lounge

FUNCTION: Space for Personnel to have lunch. **PLUMBING/PROCESS PIPING**:

SERVICE: Cold water; Sewer

SPECIAL:

FIXTURES: 2 comp. sink

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: TEMP/HUMD: Air Conditioned Environment

REQ'D: 200

OTHER:

OCCUPANTS:

EXISTING:

REQ'D: 8 Staff

ENVIRONMENT:

FLOOR: Vinyl Composition Tile (VCT)

WALL: Gypsum Board
CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.

INGRESS/EGRESS: Offices, Corridor

SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Telephone

ELECTRICAL:


LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets (GFI)



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.03 Staff Lounge				
FURNITURE/EQUIPMENT:				
TAG NO.	DESCRIPTION	QTY EXISTING	<u>REQ'D</u>	
	3'-0" x 7'-0" Table		1	
	Chairs		8	
	Built-in Counter		1	
	Whiteboards		2	





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.04 Copy / Printer Room / Mail Room

FUNCTION: Space for copy machine and network **PLUMBING/PROCESS PIPING**:

printers. SERVICE: N/A

SPECIAL: N/A **FIXTURES**: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: TEMP/HUMD: Air Conditioned Environment

REQ'D: 140

OTHER:

OCCUPANTS:

EXISTING: REQ'D: N/A

ENVIRONMENT:

FLOOR: Vinyl Composition Tile (VCT)

WALL: Gypsum Board
CEILING: Lay-In Acoustic
CEILING HEIGHT: 8'-0" min.

INGRESS/EGRESS: Offices, Corridor

SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: Data

ELECTRICAL:


LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets (GFI)



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.04 Copy / Printer Room / Mail Room				
FURNITURE/EQU	JIPMENT:			
TAG NO.	DESCRIPTION	QTY EXISTING	<u>REQ'D</u>	
	Copy Machines		2	
	Built-In Work Counter		1	
	Built-In Shelving		1	
	Network Printers		2	
	Paper Cutter and Miscellaneous		1	





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.05 Men / Women Restroom and Showers

FUNCTION: Toilet and shower facilities for **PLUMBING/PROCESS PIPING**:

Student and Staff ADA accessible. SERVICE: Hot and cold water; Sewer

SPECIAL: N/A

FIXTURES: Toilets, Sinks, Urinals, Showers

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: TEMP/HUMD: Air Conditioned Environment

REQ'D: 350

OTHER:

OCCUPANTS: EXISTING: N/A

REQ'D: N/A

ENVIRONMENT:

FLOOR: Sheet Vinyl with Cove Base

WALL: Gypsum Board with Epoxy Paint

CEILING: Gypsum Board with Epoxy Paint

CEILING HEIGHT: 8'-0" min. **INGRESS/EGRESS:** Corridor

SECURITY: N/A

COMMUNICATION:

TELEPHONE/DATA: N/A

ELECTRICAL:

LIGHTING: General Fluorescent


POWER: 110 V Power Outlets (GFI)



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.05 Men / Women Restroom and Showers				
FURNITURE/EQU	IPMENT:			
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D	
	Sink		2	
	H/C Toilet Stall		2	
	Regular Toilet Stall		1	
	Urinal		1	
	Mirror		2	
	Drinking Fountain		1	
	Shower		2	





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.06 Gender Neutral Restroom

FUNCTION: Gender neutral toilet facilities for **PLUMBING/PROCESS PIPING**:

Students and Staff. SERVICE: Cold water; Sewer

ADA Accessible. SPECIAL: N/A

FIXTURES: Toilets, Sinks, Urinals

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: TEMP/HUMD: Air Conditioned Environment

REQ'D: 125

OTHER:

OCCUPANTS:
EXISTING: N/A
REQ'D: N/A

ENVIRONMENT:

FLOOR: Sheet Vinyl with Cove Base **WALL**: Gypsum Board with Epoxy Paint **CEILING**: Gypsum Board with Epoxy Paint

CEILING HEIGHT: 8'-0" min.
INGRESS/EGRESS: Corridor

SECURITY: N/A

COMMUNICATION:

TELEPHONE/DATA: N/A

ELECTRICAL:


LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets (GFI)



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.06 Gender Neutral Restroom				
FURNITURE/EQU	IIPMENT:			
TAG NO.	DESCRIPTION	QTY EXISTING	<u>REQ'D</u>	
	Sink		1	
	H/C Toilet Stall		1	
	Urinal		1	
	Mirror		1	
	Baby Changing Table		1	





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.07 Janitor's Closet

FUNCTION: Space for janitor supplies. **PLUMBING/PROCESS PIPING**:

SERVICE: Hot and cold water; Sewer

SPECIAL:

FIXTURES: Mop sink

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: TEMP/HUMD: Air Conditioned Environment

REQ'D: 80

OTHER:

OCCUPANTS: EXISTING: N/A

REQ'D: N/A

ENVIRONMENT:

FLOOR: Sheet Vinyl with Cove Base **WALL**: Gypsum Board with Epoxy Paint

CEILING: Gypsum Board with Epoxy Paint

CEILING HEIGHT: 8'-0" min.
INGRESS/EGRESS: Corridor
SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: N/A

ELECTRICAL:

LIGHTING: General Fluorescent **POWER:** 110 V Power Outlets (GFI)




U. of A. Project No.: 06-8727

May 9, 2008

M3-PN08004

6.0 COMMON AREAS

SPACE NAME: 6.07 Janitor's Closet				
FURNITURE/EQU	JIPMENT:			
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D	
	30" x 48" Storage Shelving		2	
	Mop Sink		1	
	Mop / Broom Rack		1	





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.08 Electrical Equipment Room

FUNCTION: Space for electrical equipment. **PLUMBING/PROCESS PIPING**:

SERVICE: N/A
SPECIAL: N/A
FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: TEMP/HUMD:

REQ'D: 74 (or as required)

OTHER:

OCCUPANTS: EXISTING: N/A

REQ'D: N/A

ENVIRONMENT:

FLOOR: Sealed Concrete **WALL**: Gypsum Board

CEILING: Exposed to structure above

CEILING HEIGHT: 8'-0" min.
INGRESS/EGRESS: Corridor
SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: N/A

ELECTRICAL:


LIGHTING: Recessed light fixtures **POWER:** 110 V Power Outlets (GFI)



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.08 Electrical Equipment Room						
FURNITURE/EQU	FURNITURE/EQUIPMENT:					
TAG NO.	DESCRIPTION	QTY EXISTING	<u>REQ'D</u>			





Tucson, Arizona

M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.09 UITS Room

FUNCTION: Intermediate Distribution Closet. **PLUMBING/PROCESS PIPING**:

IDF Space SERVICE: N/A SPECIAL: N/A

FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

EXISTING: TEMP/HUMD: Air Conditioned Environment

REQ'D: 100

OTHER: 3'-0" door (to hinge outward)

OCCUPANTS: EXISTING: N/A REQ'D: N/A

ENVIRONMENT:

FLOOR: Sealed Concrete

WALL: 3/4" A-C Grade Plywood

CEILING: Exposed to structure above

CEILING HEIGHT: 8'-0" min.
INGRESS/EGRESS: Corridor
SECURITY: Lockable Door

COMMUNICATION:

TELEPHONE/DATA: N/A

ELECTRICAL:


LIGHTING: General Flourescent **POWER:** 8 20A Electrical Outlets



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.09 UITS ROOM					
FURNITURE/EQUIPMENT:					
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D		





U. of A. Project No.: 06-8727 May 9, 2008 Tucson, Arizona

6.0 COMMON AREAS

SPACE NAME: 6.10 Server Room

FUNCTION: Space for Server Equipment. PLUMBING/PROCESS PIPING:

> **SERVICE:** N/A SPECIAL: N/A FIXTURES: N/A

SQUARE FOOTAGE REQUIREMENTS: HVAC:

TEMP/HUMD: Air Conditioned Environment **EXISTING**:

REQ'D: 100 **OTHER:** 3'-0" door (to hinge outward)

OCCUPANTS: **EXISTING:** N/A REQ'D: N/A

ENVIRONMENT:

FLOOR: Sealed Concrete

WALL: 3/4" A-C Grade Plywood

CEILING: Exposed to structure above

CEILING HEIGHT: 8'-0" min. INGRESS/EGRESS: Corridor **SECURITY:** Lockable Door

COMMUNICATION:

TELEPHONE/DATA: N/A

ELECTRICAL:

LIGHTING: General Flourescent POWER: 8 20A Electrical Outlets

GROUNDING:

M3-PN08004



M3-PN08004 U. of A. Project No.: 06-8727 May 9, 2008

6.0 COMMON AREAS

SPACE NAME: 6.10 Server Room					
FURNITURE/EQUIPMENT:					
TAG NO.	DESCRIPTION	QTY EXISTING	REQ'D		

